

Date of Issue: October 9, 2017

Affected Publication: API Specification 7K, *Drilling and Well Servicing Equipment*, Sixth Edition, December 2015

ERRATA 3

Page 29, Section 8.4.7.4.2, the fourth bullet shall be amended:

- no relevant indications in pressure-sealing areas, in the root area of rotary threads, or in the stress-relief features of threaded joints.