

Date of Issue: June 2019

Affected Publication: API Specification 19G1, *Side-pocket Mandrels*, Second Edition, February 2019

Errata 1

Page 36: Section B.1.4.7 shall be replaced with the following:

Perform B.1.3.7.